



SECOR
INTERNATIONAL
INCORPORATED

www.secor.com

2655 Camino Del Rio N. Suite 302
San Diego, CA 92108
619-296-6195 TEL
619-296-6199 FAX

December 13, 2005

Project No. 08BP.06061.05

County of San Diego, Department of Environmental Health,
Land and Water Quality Division (LWQD)
Well Permit Desk
P.O. Box 129261
San Diego, CA 92112-9261

Attention: Permit Clerk

Subject: Well Destruction Compliance
ARCO Facility #6061
593 North Mollison Avenue
El Cajon, California 92021
SAM Case No. H07106-001
Well Destruction Permit # LMON102796

On behalf of the Atlantic Richfield Company (Atlantic Richfield), SECOR International Incorporated (SECOR) is submitting this response letter to the County of San Diego, Land and Water Quality Division (LWQD) regarding the Monitoring Well Compliance/Drilling Inspection Report dated November 3, 2005 (attached). The LWQD inspection report indicated that monitoring well W-9A was a safety concern due to settling of the well backfill materials. The LWQD therefore requested that the deficiency be corrected using soil to backfill the hole. On December 5, 2005, SECOR personnel backfilled the area of W-9A with approximately 16 quarts of soil, moistened the soil with water and tamped it down. Photographs of W-9A with the repairs are attached.


If you have any questions or comments regarding this letter, please contact the undersigned.

Sincerely,

SECOR International Incorporated

Melissa Garrett
Environmental Scientist

Carole M. Farr, PG #7434
Senior Geologist



cc: Manuel Marquez, West Hazmat Drilling dba Test America
Roy Thun, Atlantic Richfield Company

Attachments: Department of Environmental Health, Monitoring Well Compliance/Drilling
Inspection Report
Site Plan (Figure1)
Photographs



DEPARTMENT OF ENVIRONMENTAL HEALTH
MONITORING WELL COMPLIANCE/DRILLING
INSPECTION REPORT

APN : 483-380-36, -41

PERMIT# LMON102796

EST.# H07106-001

INSPECTION DATE: 11/3/2005

NOV 21 2005

SECOR INTERNATIONAL

RESPONSIBLE PARTY: ATLANTIC RICHFIELD CO.

ATTN: ROY THUN

4 CENTER POINTE DR

LA PALMA, CA 90623

SITE NAME: ARCO STA. #6061 & OFF SITE

SITE ADDRESS: 593,596 N MOLLISON

EL CAJON, CA 92021

MONITORING WELL	VADOSE WELL	BORING	DESTRUCTIONS	AIR SPARGE WELL
			23	

CONSULTANT: SECOR INTERNATIONAL

DRILLING CO: WEST HAZMAT

WELL LOCATION NUMBER	W-1, W-3 > W-11	SW-1 > SW-6	HVW-1 > HVW-4	RW-1, VW-1	SOW-1
COMPLETED					

REMARKS:- MWP STAFF WERE NOT PRESENT DURING THE DESTRUCTION DRILLING ACTIVITIES. HOWEVER, BASED ON REVIEW OF THE 60-DAY DRILLING REPORT AND THIS SITE INSPECTION, THE 23 MONITORING WELLS APPEAR TO HAVE BEEN PROPERLY DESTROYED WITH THE FOLLOWING EXCEPTION:

BENTONITE BACKFILL FOR DESTROYED WELL W-9A APPEARS TO HAVE SETTLED, CREATING A SAFETY HAZARD. SEE ATTACHED PICTURE.

THE WELL DEFICIENCIES MUST BE CORRECTED AS STATED BELOW AND THE INSPECTOR NOTIFIED BY NOVEMBER 30, 2005.

1. PLACE SOIL IN MW-9A FROM THE DEPTH OF THE HOLE TO THE GROUND SURFACE TO MATCH THE SURROUNDING AREA. ENSURE SOIL IS COMPACTED SUFFICIENTLY THAT IT WILL NOT PRESENT A TRIPPING HAZARD.

RETURN A COPY OF THIS REPORT WITH YOUR SIGNATURE BY THE DATE STATED ABOVE TO CONFIRM THAT THE WELL DEFICIENCIES HAVE BEEN CORRECTED. IF YOU HAVE ANY QUESTIONS PLEASE CONTACT ME

Marisue Crystal, Environmental Health Technician

Phone: (619) 338-2013


cc: CAROLE FARR, SECOR INTERNATIONAL

I confirm that the well deficiencies stated above have been corrected/repaired on

(Date)

(Print Name)


(Signature)



WELL	SCREEN	HOOKE UP TO SVE OR AS SYSTEM
W-1	5'-10'	NO
W-3	5'-20'	NO
W-4	5'-22'	NO
W-5	5'-20'	NO
W-6	5'-20'	NO
W-7	5'-20'	NO
W-8A	4'-19'	NO
W-10A	4'-19'	NO
W-8	5'-20'	NO
W-9	4'-19'	NO
W-10	4'-19'	NO
MW-11	5'-20'	NO
RW-1	5'-25'	NO
VW-1	5'-10'	NO
HVW-1	HORIZ. 04'	YES
HVW-2	HORIZ. 04'	YES
HVW-3	HORIZ. 04'	YES
HVW-4	HORIZ. 04'	YES
SW-1	17'-19'	YES
SW-2	17'-19'	YES
SW-3	17'-19'	YES
SW-4	21'-24'	YES
SW-5	17'-20'	YES
SW-6	18'-19.5'	YES
SOW-1	17'-19'	NO

LEGEND:

- MONITORING WELL
- ⊕ VAPOR EXTRACTION WELL
- HORIZONTAL VAPOR EXTRACTION WELL
- ▲ AIR SPARGE WELL
- ⊗ ABANDONED MONITORING WELL
- SOIL BORING
- ⬜ PLANTER
- ⬜ PROPERTY LINE
- ⬜ UNDERGROUND STORAGE TANK




 2855 CAMINO DEL RIO NORTH, SUITE 302 SAN DIEGO, CALIFORNIA PHONE: (619) 296-6185/296-6188 (FAX)	FOR:		ARCO FACILITY #6061 693 North Mollison Avenue El Cajon, California		FIGURE: 1
	JOB NUMBER: 08BP.08061.04	DRAWN BY: PD	CHECKED BY:	APPROVED BY:	
DATE: 8/19/05					

**SECOR
PHOTOGRAPHIC RECORD**

Client:	Atlantic Richfield	Job Number:	08BP.06061.05
Subject Name:	ARCO Facility #6061	Location:	596 North Mollison Avenue El Cajon, CA 92021
Photographer:	Melissa Garrett	Date:	December 5, 2005

Photograph No. 1



Backfilled location of well W-9A.

Photograph No. 2



Close up view of backfilled location of well W-9A.